

Maillon used during a radial test to destruction. The maillon deformed after as we undone the screw thread. Note the movement of metal from the contact area with the Eco anchor



This alloy karabiner had been left attached to an Eco anchor at the bottom of a small waterfall for about 3 months

